



TRUCK ROUTE



Drivers of trucks and delivery vehicles must have the following safety equipment:



Safety vests in accordance with  
DIN EN ISO 20471



Safety shoes in accordance with  
DIN EN ISO 20345

**PLEASE NOTE:**

The safety vest and safety shoes must be worn when leaving the vehicle and while on the premises.

**JELBA**

Werkzeug & Maschinenbau

**JELBA GmbH & Co. KG**

Brünststraße 6  
94051 Hauzenberg-Jahrdorf, Germany

e-mail: [info@jelba.de](mailto:info@jelba.de)

**Tel.:** + 49 (0) 8586 - 96 38 - 0

**Fax:** + 49 (0) 8586 - 96 38 - 80

[www.jelba.de](http://www.jelba.de)



**SAFETY INFORMATION FOR  
FACTORY VISITORS**

**JELBA**

Werkzeug & Maschinenbau



In the interests of your safety and to protect against the specific hazards of a mechanical engineering company or a plant for machining large parts, we have compiled this safety information for you.

It contains the essential safety regulations and applies to all third-party employees who are staying on the factory premises and in the buildings of JELBA GmbH & Co. KG.

Read the instructions carefully and act accordingly.

Please always be in touch with your contact person at JELBA.

The instructions of the security staff on the factory premises must be followed.

For employees of external companies, further regulations, e.g. the work rules shall apply.

**We wish you a safe and pleasant stay.**



On the entire factory premises is a general ban on picture and sound recordings (also applies to mobile phones). Cameras (both for film and still photography) may not be carried.



Please only stay there, where you are guided by your contact person.



During the period of your stay in the plant designated smoking bans must be strictly observed.



The switching of machines and systems is prohibited. Keep away from the working area of the machines and make sure that our employees can carry out their work undisturbed.



Throughout the plant there is a high volume of traffic on the factory roads and the transport routes within the production areas. Do not stand at crossings or in building entrances or exits.



Production parts can be sharp-edged or subject to special quality requirements. They must not be touched without explicit permission.



Suspended loads pose serious hazards. Keep away from workpieces that are transported with cranes and do not step under the suspended load.



Safety shoes must be worn when leaving the main traffic routes or visitor routes. Depending on the hazard potential or marking of the plant areas, additional protective equipment must be worn.



Emergency call external (0)112



Fire brigade external (0)112



First aider (Safety Officer S. Zillner) DW. - 22

Company Doctor (Dr. Schweller) (0)08591-1814

Safety Protection (Weiß) (0)08585-969511



In case of evacuation, the alarm signals are to be observed (siren, megaphone, light signals).



Leave the areas on the designated escape and rescue routes.



Go directly to the collection points and wait for further instructions or orders.



On the premises the road traffic regulations shall apply. The maximum speed is 10 km/h. Forklift vehicles have priority. Crane movements and vehicle traffic are to be observed.



The parking of motor vehicles is only allowed on marked parking lots.